ICS 209 (C	Oil Spill)	- Incide	nt Stat	us Sun	nmary	,			,	Version N	lame: 2	0191228
Incident Name: South 4 Group Fire				Period: Period 16 [12/19/2019 06:00 - 01/31/2020 06:00								
Spill Status (Estimated)				Equi	ipment R	esource:	5					
Source Stat	us Rem	aining po	tential		1	51,740	Kind	Ordered	Available	Assigned		Tota
SECURED	Rate	of spillag	je		0 b	arrel(s)	Ain Marriton MultiDAE			40	Service	
	Volu	mes mea	sured in		b	arrel(s)	Air Monitor - MultiRAE	0	0	ļ	0	10
		Sinc	e Last R	eport		Total	Air Monitor - UltraRAE	0	0	0	0	<u> </u>
Total Volume	e Spilled			0		999	Boom Fire Fighting Foom	0	1,590	2,000	0	2,001 1,590
Mass Balan	ce (Estim	ated)		Volume	s in ga	llon(s)	Fire Fighting Foam Jon Boat	0	1,590	0	1	1,590
Recovered Mat	erial (Liquid		1	5,000		76,500	Pumps	2	21	35	0	58
Foam				0	***************************************	1,320	Response Boat	0	0	2	0	2
Combusted Ma	terial (bbl)			0		48,970	Skimmer	0	17	1	0	18
Waste (Esti	mated)						Sorbent: Boom	0	50	8,350	0	8,400
Туре		Recove	red S	Stored D	isposed	UOM	UTV	0	0	0,330	1	0,400
Sorbent: Boom		13,7	720			Feet	Vacuum Truck	0	0	9	3	12
Debris		1,2	287			Bags		4	17	108	1	130
Liquid		218,7	725			gallon	Viscous Sweep	0	- 17	250	0	250
						(s)		Personn			U	230
Shoreline Ir	npacts		Di	stances		ıred in mile(s)					in To	tal Dagala
Degree of O	ilina	Δff	ected	Cleaned		aining to	Organization	Peop	le in the Field	People Cmd. F		tal People On Scene
Dogree or O	mig		colou	Oleanea		Cleaned	Other		2		0	2
		Wildlife	Impacts		•		Federal		0		0	C
					Died In	Facility	State		2		0	2
Туре	Captured	Cleaned	Released	DOA	Euth.	Other	Local		8		0	8
Fish Above 3"	, 0	0	0	68	0	0	RP		126		30	156
Bird	0	0	0	0	0	0	Contract Personnel		431		34	465
Mammal	0	0	0	0	0	0	Totals		569		64	633
Reptile	0	0	0	1	0	0		Spec	ial Note:	S		
2-3" Fish	0	0	0	2,000	0	0	Active Fires: 1	•				
Blue Crab	0	0	0	18	0	0						
Pig				2			Notes:					
Turtle				1			*Spilled material based o	n 98% dest	ruction effic	ciency of th	e fire.	
	1	Safety	Status	1		1	NO CIR's					
Туре		Amou	ınt since la	st report	Totai	Amount						
Public Injury	***************************************			0		0						
Responder Inju	rv			1		5						
Community Air Readings for all analytes		0	1	10,000								
BD - Community Air 0 Detections above action level		0		238								
Community Air Monitoring readings for Butadiene				38,501								
VOC - Commu Detections abo	nity Air			0		11						
ICS 209 (Oil	Spill) - In	cident St	atus Sun	nmarv			Prepared By Planning	Section, I	Jpdated 1	2/28/2019) 22:10 U	TC -6: PI
INCIDENT ACTI				2/28/2019 2	2:23 UTC	-6:00	1 of 7	-	Ì			© TRG

Incident Name: South 4	Group Fire	nmary	Pariod: Pariod 46 (40/40	/2010 06:00 - 01/21/2020 06:0
Incident Name: South 4			Penod: Penod 16 [12/19	/2019 06:00 - 01/31/2020 06:0
Tuno	Safety Status	Total Amount		
Туре	Amount since last report	Total Amount		
Community Air Monitoring eadings for VOC		38,769		
S 209 (Oil Spill) - Inc	ident Status Summary		renated By Planning Section 11st	odated 12/28/2019 22:10 UTC -6: i
20 You (Ou Shiii) - Ilic	went status sunninary	l P	repared by Framming Section, Up	maicu 12/20/2018 22.10 010 -0.1

Daily Summary – TPC Port Neches South 4 Group Fire 12/28/2019

The waterway has now transitioned to Maintenance and Monitoring Mode

Shoreline Impacts	Assessed, miles	In Remediation, miles	Sign Off
No Oil Observed	4.96		4.96
Light Oil	1.05		1.05
SCAT Recommends No	2.58		2.58
Further Treatment			

- There were no CIR's issued today.
- There were no new leaks identified.
- For more than twelve days, there have been no readings above detection limits for butadiene. There was no VOC readings above detection limits for more than 24 hours. Community air monitoring for Butadiene and VOC continues to be performed 24/7 within the ½-mile radius of the site.
- Water, totaling approximately 2400 gpm, continues to be sprayed on 3 areas to help reduce concentrations of butadiene within the work zone. We are monitoring the 201 Outfall frequently to minimize any overflow of the weir.
- Work Zone recovery of PACM/ACM material continued. Wipe tests were collected per the Building ACM Plan.
 No results have been reported.
- There was no DEHA injection on 12/28.
- The drone flew only one observation run in the afternoon because of weather conditions. There new no issues identified.
- CTEH will provide a comprehensive summary of all water analyses by 12/30/2019.
- The following table provides a list of ongoing leaks have been identified on lines associated with the following:

Tank Number/Equipment Type	Material in Tank	Component Involved	Repaired
39	Raffinate	Flange on line east of sphere 39	
40	Raffinate	Tubing valve	12/14/2019
36	High Butane Raffinate	Flange on tank	
33	High Butane Raffinate	Tubing fitting. Leak under tank not accessible.	
35	High Butane Raffinate	Tubing leak	
90 & 91	High Purity Butadiene	Leak on common suction line, 092 that runs N to S	
26 Crude C4		Line leak, attempted repair with clamp	12/14/2019
30	Water and NMP Solvent	Tubing fitting	12/13/2019
219	МТВЕ	Vacuum Breaker, Intermittent	
2" Flange SE corner of block 10	Assumed BD	Flange	
6" valve at block 5 on 3 rd street	Raff	Valve	12/17/2019
Tank 42 Relief Valve	Raff	Relief Valve	

Tank Number/Equipment Type	Material in Tank	Component Involved	Repaired
2-Six-inch line leaks where Tank 34	Raffinate, High BD	Line Leak	
1-6" Line (originally thought to be 2-10" lines to process compressor)	High BD concentration,	Damaged piping	
Tank 220	MTBE	Vacuum Breaker	
3" Line in Block 5	Assumed BD	Line Leak	
3" flange SW of 33tk on 2 nd St.	Assumed BD	Flange	

• The Outfall Canal remains in Monitoring and Maintenance mode. Water was approximately 1' below the Outfall 201 weir.

Upcoming Activities

- US Coast Guard will conduct a full inspection at the dock before the system is utilized for loading operations. Plans are being implemented to prepare the dock line for the hydrostatic testing.
- Monitoring of the schools has been suspended during Holiday Break, but the area will continue to be monitored as part of the 1/2 -mile radius Air Monitoring Plan.
- The Potential Asbestos Containing Material (PACM) Cleanup Team continues collecting material found on the ground, per the approved plan. They will continue the work but will not remediate the area or disturb the evidence. The teams will start at the north end of the site, collecting the material in a planned manner until the whole site has been completed.
- The two-way traffic pattern changed today on 366 (per plan) at 0600 and is flowing smoothly.
- The Technical Teams continue to develop and review the plans that are being developed ultimately de-inventory equipment at the site. The plan is to begin purging the dock line Monday morning in preparation for dock line hydrotest.

Health and Safety

No issues.

Water Effluent

Status of 201: 1' below the weir.

GPM to JWWTP: 0 gpm.

Water Testing: Analytical summaries will be provided each Monday

- As of December 21, 2019, a total of 222 surface water samples have been collected at 21 different locations for VOCs, SVOCs, PAH, PFAS, TPH, TOC, oil and grease, ethylene glycol, and asbestos analysis. Results of these analyses are not representative of drinking water sources.
- As of December 21, 2019, 197 surface water sample results have been received for VOC analysis and 131 results received for asbestos analysis.
- There have been no exceedances of TCEQ Contact Recreation Water Protective Concentration Limit (PCL) screening levels for the surface water samples with available PCLs. Where no PCLs are available, results are being compared to background surface water samples.

Wildlife Report

• There were no Wildlife reports on 12/28/2019

Recovery Operations

• Routine monitoring.

SCAT Report

• Maintenance and Monitoring Plan is in effect.

Waste No changes 12/28/2019.

Profiles are being developed and disposal options identified for the waste that has been collected outside of the site.

Gallons	Frac Tanks (20,000 gallons capacity)	# Of Tanks Used
177,500	Liquids from outfall canal skimming	9
10,000	Water and hydrocarbons from south separator	.5
30,000	Latex-laden Wastewater from LION	1.5
15,000	Hydrocarbons from API Separator	0.75
250	Wash Water from decon at Vallen Trailer	0.1
10,000	Liquids from Second Street Ditch	0.5
	Empty Available and Staged	5
235,250	Totals	19

CYD's	Potential Asbestos Containing Material (PACM)	# Of Boxes Used
12.5	Material from 201 outfall and south separator	0.5
30	Motiva (1-full, 1-in use)	2
6.25	Joint Waste Water	1
48.75	Totals	4

CYD's	Roll Off Boxes (25 CYD's capacity)	# Of Boxes Used
225	Hydrocarbon Debris and Sorbents from Canal	11
225	Totals	11

Other	
Routine Plant Trash (Garbage)	1
Dirty Containment Boom waiting on decon	0

Empty available and staged (requested 4 more) 2

Worksite Air Monitoring

During this reporting period, all detections above the site-specific action levels were investigated as outlined in the SAP approved by UC. No detections of %LEL were observed within the work area during this reporting periods. There were 4 detections of both VOC and Butadiene.

Community Air Monitoring

Please note: Air monitoring samples will continue to be collected, but analytical results will be reported once per week on Monday.

Asbestos Monitoring

Community

- Wipe samples: Five of the 308 samples collected have been positive for asbestos
- Bulk Sampling: 171 of 373 samples tested positive for asbestos

Air Monitoring Sampling Results

Community

The analytical information below represents data as of 12/21/2019, as provided on 12/23.

Analytical	Detections	Samples Collected	Sample Stations
Volatile Organic Compounds (VOC)*	2*	503	54
Poly Aromatic Hydrocarbons (PAH)	None Detected	476	28
Asbestos	1**	891	44

^{2*} There were detectable amounts of VOC, but two were above the Texas Commission on Environmental Quality (TCEQ) 24-hour AMCV (430 ppb), however below the TCEQ short-term AMCV (1,700 ppb).

Community Assessments

Please reference the next page for this community assessment information.

^{**} The analysis has not been verified by second-level evaluation

Community Property Assessment Summary

281 114 229

Count of Industrial Debris Claims Count of Properties with Observed Count of Properties with Observed Sampled Damage Debris

Community Property Assessment Summary - Jefferson

250 108 200

Count of Industrial Debris Claims Count of Properties with Observed Count of Properties with Observed

Sampled Damage Debris

Community Property Assessment Summary - Orange

31 6 29

Count of Industrial Debris Claims Count of Properties with Observed Count of Properties with Observed Sampled Damage Debris

Completed Property Assessments Property Type Sum

Type	# of Properties
Commercial/Business Multi-family Residence	3
Single Family Home	276
	281